AUG 2 9 2005 W

10/688632

age

Docket No.: SPINE 3.0-455 CIP (PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Errico et al.

Patent No.: 6,896,676 \$2

Issued: May 24, 2005

Certificate

For: INSTRUMENTATION AND METHODS FOR

USE IN IMPLANTING A CERVICALDISC

REPLACEMENTDEVICE

SEP 0 1 2005 of Correction

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: August 26, 2005

Respectfully submitted,

Michael J. Doherty

Registration No.: 40,592

LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

600 South Avenue West

Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

586116_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1_

PATENT NO.

6,896,676

APPLICATION NO.

10/688,632

ISSUE DATE

May 24, 2005

INVENTOR(S)

Joseph P. Errico, Michael W. Dudasik, and Rafail Zubok

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**Column 2, line 4, utilied should read --utilized--.
Column 11, line 54, delete "a" after the word "with".
Column 19, line 9, delete "a" after the word "by".
Column 19, line 29, 1a-e, should read --11a-e--.
Column 20, line 13, views: should read --views--.
Column 24, line 33, screw should read --screws--.**

MAILING ADDRESS OF SENDER (Please do not use customer number below): Michael J. Doherty LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West

No. of additional copies 1

Westfield, New Jersey 07090